

Map ID
Direction
Distance
Elevation

MAP FINDINGS

EDR ID Number
EPA ID Number

LI1549
NNW
> 1
1.957 mi.
10333 ft.

TWO GALLONS OIL IN MANHOLE 6900
8646 20 AVENUE
BROOKLYN, NY

NY Spills S108297470
N/A

Site 1 of 2 in cluster LI

Relative:
Higher

Actual:
56 ft.

SPILLS:

Name: TWO GALLONS OIL IN MANHOLE 6900
Address: 8646 20 AVENUE
City,State,Zip: BROOKLYN, NY
Spill Number/Closed Date: 0611403 / 2007-06-28
Facility ID: 0611403
Facility Type: ER
DER Facility ID: 325632
Site ID: 376039
DEC Region: 2
Spill Cause: Unknown
Spill Class: C4
SWIS: 2401
Spill Date: 2007-01-12
Investigator: GDBREEN
Referred To: Not reported
Reported to Dept: 2007-01-14
CID: 78
Water Affected: Not reported
Spill Source: Unknown
Spill Notifier: Local Agency
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 2007-01-14
Spill Record Last Update: 2007-06-28
Spiller Name: Not reported
Spiller Company: Con Edison
Spiller Address: Not reported
Spiller Company: 001
Contact Name: ERT
DEC Memo: "06/28/07 - See eDocs for Con Ed report detailing cleanup and closure. 204056. see eDocs"

Remarks: "no clean up due to D fault no to 5 questions 204056"

All Materials:

Site ID: 376039
Operable Unit ID: 1133649
Operable Unit: 01
Material ID: 2123468
Material Code: 0066A
Material Name: unknown petroleum
Case No.: Not reported
Material FA: Petroleum
Quantity: 2.00
Units: G
Recovered: .00
Oxygenate: Not reported